### CITY of ALBUQUERQUE TWENTY THIRD COUNCIL

COUNCIL BILL NO. <u>R-19-153</u> ENACTMENT NO.

SPONSORED BY: Pat Davis, by request

#### RESOLUTION

A NUISANCE, SUBSTANDARD DWELLING OR STRUCTURE IN NEED OF
ABATEMENT AT 247 ESPANOLA ST NE 87108 WITHIN THE CITY LIMITS OF
ALBUQUERQUE, NEW MEXICO IS SO RUINED, DAMAGED AND DILAPIDATED
AS TO BE A MENACE TO THE PUBLIC COMFORT, HEALTH, PEACE OR
SAFETY AND THAT IT IS TO BE REQUIRED TO BE REMOVED.

7 WHEREAS, the building, structure or premises is located at 247 8 ESPANOLA ST NE ALBUQUERQUE NM 87108, which is located and is more 9 particularly described as: \*00260004LA MESA SUBD; and

10 WHEREAS, the Planning Department, Code Enforcement Division of the 11 City of Albuquerque has investigated the condition of said Building, structure 12 of premises and has found same to be so ruined, damaged and dilapidated 13 that it constitutes a menace to the public comfort, health, peace or safety and 14 warrants abatement and removal.

15 BE IT RESOLVED BY THE COUNCIL, THE GOVERNING BODY OF THE CITY OF16 ALBUQUERQUE:

Section 1. That the findings of said Code Enforcement, in regard to said building, structure or premises, be and are hereby approved and adopted and that said building, structure or premises is found to be ruined, damaged and dilapidated, as to be a menace to the public comfort, health, peace or safety pursuant to Section 3-18-5, N.M.S.A., 1978.

22 Section 2. That SHAIN LAWRENCE V & RACHEL R, record owner of said 23 building, structure or premises shall commence removal of same within ten 24 (10) days after service of a copy of this Resolution or within said ten (10) day 25 period, file written objection to findings herein with the City Clerk/Recorder of 26 the City of Albuquerque, asking for a hearing before the City Council.

1

Section 3. If there is a failure of compliance with the provision of Section 2 herein, the City of Albuquerque shall proceed to remove said building, structure or premises and abate said unsafe condition and the cost thereof shall constitute a lien against such property so removed and against said lot or parcel of land from which such removal be made, all as required and allowed by law

Section 4. SEVERABILITY CLAUSE. If any section, paragraph, sentence, clause, word or phrase of this resolution is for any reason held to be invalid or unenforceable by any court of competent jurisdiction, such decision shall not affect the validity of the remaining provisions of this resolution. The Council hereby declares that it would have passed this resolution and each section, paragraph, sentence, clause, word or phrase thereof irrespective of any provisions being declared unconstitutional or otherwise invalid.

- 14
- 15
- 16 17

18

19

20

21

22

- [Bracketed/Underscored Material] New Bracketed/Strikethrough Material] - Deletion
  - 23 24 25 26 27 28 29 30 31
  - 32



CITY OF ALBUQUERQUE Albuquerque, New Mexico Office of the Mayor

Mayor Timothy M. Keller

#### **INTER-OFFICE MEMORANDUM**

Date: April 25, 2019

TO: Klarissa J. Peña, President, City Council

FROM: Timothy M. Keller, Mayor

SUBJECT: Resolution of Nuisance Abatement of a Substandard Building at: 247 Espanola St NE

The attached resolution requests that the building located at 247 Espanola St NE, Albuquerque, New Mexico 87108, be abated and removed. Council approval is required according to N.M.S.A. Section 3-18-5, 1978.

In the event that the owners fail to demolish the condemned structure, the Planning Department will contract for the demolition and place a lien on the property. The estimated cost for demolition is \$24,500.

I am submitting this resolution to the City Council for their consideration and action.

<u>5/22</u>/19 Date

Resolution of Nuisance Abatement of a Substandard Building at: 247 Espanola St NE, Albuquerque, New Mexico 87108

Approved:

Sarita Nair Chief Administrative Officer

Recomn David S. Campbel Planning Director

Approved as to Legal Form:

Esteban guila

City Attorney

1. What is it?

A substandard, nuisance structure located at 247 ESPANOLA ST NE 87108 and legally described as, \*00260004LA MESA SUBD, in the City of Albuquerque.

2. What will this piece of legislation do?

Enable the removal of an unsafe, substandard, nuisance structure by a City Agency.

3. Why is this project needed?

Council approval is required for demolition of a Nuisance structure according to N.M.S.A. Section 3-18-5, 1998 and City Ordinance

4. How much will it cost and what is the funding source?

The estimated cost is \$24,500 from the General Fund. Upon completion of demolition, a lien will be filed which includes a demand for payment addressed to said owner(s).

5. Is there a revenue source associated with this Plan? If so, what level of income is projected?

None

#### **FISCAL IMPACT ANALYSIS**

#### TITLE: 247 Espanola St NE \*00260004LA MESA SUBD

<u>R: X O:</u> FUND: 110

DEPT: Planning

- No measurable fiscal impact is anticipated, i.e., no impact on fund balance over and above existing appropriations.
- [] (If Applicable) The estimated fiscal impact (defined as impact over and above existing appropriations) of this legislation is as follows:

			2019	Fi	scal Years 2020	2	2021	Tot	tal
Base Salary/Wages Fringe Benefit: Subtotal Personnel	30.440%		-		-	<u> </u>			- - -
Operating Expenses Property	0/				-		-		- -
Indirect Costs	%								-
Total Expenses		\$	-	\$	-	\$	-	\$	-
[] Estimated revenues ( [X] Estimated revenue in									
					-		-		-
									•
									-
Total Revenue		\$		\$		\$	-	\$	
These estimates do r	not include any	adjustmen	t for inflatio	<b>•</b>	**** *	<b>`</b>		<b>*</b>	

\* Range if not easily quantifiable.

Number of Positions created

#### COMMENTS :

Structure poses an extreme hazard and is substandard and a nuisance to the neighborhood surrounding community and to inquisitive minors. The structure will continue to dilapidate causing life safety issues. This is a substandard and a nuisance property.

#### COMMENTS ON NON-MONETARY IMPACTS TO COMMUNITY/CITY GOVERNMENT:

PREPARED BY:


**FISCAL ANALYST** 

**REVIEWED BY:** 


EXECU ANALYST

(date)

5128/19 BUDGE OFFICER (date)



N



CODE ENFORCEMENT Plaza Del Sol Building, Suite 500 600 2<sup>nd</sup> Street NW Albuquerque, NM 87102 Tel: (505) 924-3850 Fax: (505) 924-3847



Richard J. Berry, Mayor

Oct 2, 2017

NOTICE AND ORDER WITH APPEAL

#### SHAIN LAWRENCE V ETUX 1749 ALLEGHENY DR NE RIO RANCHO, NM 87144

Dear Property Owner:

The City of Albuquerque Planning Department, Code Enforcement Division, made an inspection of the building or structure owned, occupied, or controlled by you at: **247 ESPANOLA ST NE, Albuquerque, NM 87108** on Sep 30, 2017

The Property is more particularly described as:

LOT 26, BLOCK 4, SUBDIVISION LA MESA

Violations of the Uniform Housing Code, hereafter 'Code', City Council Ordinance No. 34-1986 and codified at 14-3-1-1 et seq ROA 1994, were found that must be corrected in order to maintain the accepted standards of health and safety provided for in the Code.

FINDINGS

The Code Enforcement Section has found the units to be substandard under the provisions of the Code. The findings of the inspection are as listed on the following page.

Sincerely,

Christopher Romero Code Enforcement Specialist (505) 924-3363

1 In how he

File Number: CF-2017-026233

Initial Print Date: Oct 2, 2017

Job Number: 049887118-001

CODE ENFORCEMENT Plaza Del Sol Building, Suite 500 600 2<sup>nd</sup> Street NW Albuquerque, NM 87102 Tel: (505) 924-3850 Fax: (505) 924-3847



Richard J. Berry, Mayor

#### Description of Violation(s) found on the property located at: Address: <u>247 ESPANOLA ST NE, Albuquerque, NM 87108</u>

The above-described premises have been inspected and the following violations of City laws and regulations have been found:

Violation Type	Violation Description	<b>Resolve By Date</b>
14-3-4-3 Structural	All holes in walls throughout the dwelling shall be repaired and	Oct 30, 2017
Hazards	repainted. Replace all damaged walls, ceilings throughout	
	dwelling to include replacing all damaged or missing insulation	
	and sheet rock. All shall be replaced to include taping, texturing	
	and repainting, prior to being occupied.	
14-3-3-2	At the time of inspection the dwelling unit was without gas	Oct 30, 2017
Mechanical	services and heat. Prior to dwelling being occupied, gas services	
Requirements	shall be restored by NM Gas Company.	
14-3-4-4 Nuisance	At the time of inspection there were 5 open windows and 3 open doors.	Oct 30, 2017
	All broken and or missing windows and doors shall be repaired	
	or replaced to open close and lock as designed, prior to the	
	dwelling being occupied.	
14-3-4-13	Prior to occupancy, all bedrooms, hallways and rooms for living	Oct 30, 2017
Inadequate Fire-	shall be provided with functioning smoke detectors.	
Protection		
14-3-4-1	The subject property is an abandoned dwelling that was	Oct 30, 2017
Substandard	unsecured and vacant lacking electrical and gas services causing	
Building Defined	the dwelling to be substandard. Electrical and gas shall be	
	reactivated by the proper utility company prior to occupancy.	
	The dwelling was vandalized and upon inspection it was found	
	that the dwelling contained graffiti on several interior walls,	
	broken windows, broken fixtures and broken doors.	
14-3-4-4 Nuisance	This office was contacted by the Albuquerque Police	Oct 30, 2017
	Department multiple times due to the dwelling being found in a	
	unsecured and being used by transients. The broken doors and	
	unsecured openings were allowing trespassers and malicious	
	mischief. The accumulation of discarded items, trash, syringes	
	and weeds make this property an eyesore to the surrounding	
	neighborhood. This unsecured and apparently vacant home	
	required immediate securing for public safety purposes on	

File Number: CF-2017-026233

Initial Print Date: Oct 2, 2017

Job Number: 0

049887118-001

THE WELL

CODE ENFORCEMENT Plaza Del Sol Building, Suite 500 600 2<sup>nd</sup> Street NW Albuquerque, NM 87102 Tel: (505) 924-3850 Fax: (505) 924-38.

Tel: (505) 924-3850 Fax: (5	05) 924-3847	Richard J. Berry, Mayor
	September 29, 2017. While vacant, the structure shall remain	
	secure with the exterior free of weeds and litter. You must then	
	repair or demolish the building or structure.	

Code Sections	Code Description
14-3-4-3(K)	Every interior wall and ceiling is free of holes and large cracks. Every interior wall
	and ceiling is free of loose plaster and other structural material, the collapse of
	which might constitute an accident hazard. Plaster, paint, and all other surface
	materials are of such character as to be easily cleanable and are reasonably smooth,
	clean, and tight.
14-3-3-2(A)(1)(a)	Every dwelling unit and guest room shall be provided with heating facilities capable
	of maintaining a room temperature of 70° F. at a point 3 feet above the floor in all
	habitable rooms. Such facilities shall be installed and maintained in a safe condition
	and in accordance with Chapter 37 of the Building Code and the Mechanical Code
	(adopted in § 14-1-3) and all other applicable laws.
14-3-4-4(B)	Buildings that have broken windows or doors constituting hazardous conditions and
	inviting trespassers or malicious mischief.
14-3-4-13	INADEQUATE FIRE-PROTECTION or FIREFIGHTING EQUIPMENT shall include all
	buildings or portions thereof which are not provided with the fire-resistive
	construction or fire-extinguishing systems or equipment required by this code and
	the Chief of the Fire Department, except those buildings or portions thereof which
	conformed with all applicable laws at the time of their construction and whose fire-
	resistive integrity and fire-extinguishing systems or equipment have been
	adequately maintained and improved in relation to any increase in occupant load,
· · · · · · · · · · · · · · · · · · ·	alteration or addition, or any change in occupancy.
14-3-4-1	Any building or portion thereof, including any dwelling unit, guest room or suite of
	rooms, or the premises on which the same is located, in which there exists any of
	the following listed conditions [set forth in §§ 14-3-4-2 et seq.] to an extent that
	endangers the life, limb, health, property, safety or welfare of the public or the
	occupants thereof shall be deemed and declared a SUBSTANDARD BUILDING.
14-3-4-4(E)	Buildings in an unsecured state that are not securely fenced or adequately lighted to
	prevent access to trespassers, criminals or others unauthorized to enter for the
	purpose of committing a nuisance or unlawful act or that constitutes an attractive
	nuisance for children.

Initial Print Date: Oct 2, 2017

CODE ENFORCEMENT Plaza Del Sol Building, Suite 500

600 2<sup>nd</sup> Street NW Albuquerque, NM 87102 Tel: (505) 924-3850 Fax: (505) 924-3847

Richard J. Berry, Mayor

ORDER

You, as the owner of the building or structure, are hereby ordered to:

This unsecured and apparently abandoned home required immediate securing for public safety purposes on September 29, 2017 and the property has been posted substandard. While vacant, the structure shall remain secure with the exterior free of weeds and litter. You must then repair or demolish the building or structure. In repairing or demolishing the building or structure, obtain all required permits. The repairs must be completed by November 2, 2017

#### NOTICE ADMINISTRATIVE REMEDIES

IF NO APPEAL IS FILED BY THE EFFECTIVE DATE OF THIS NOTICE AND ORDER, THE CITY MAY CAUSE ANY STRUCTURES TO BE SECURED AND ALL TRASH AND DEBRIS REMOVED WITHOUT FURTHER NOTICE TO ANY PARTY, AND A LIEN WILL BE PLACED AGAINST THE PROPERTY FOR THE CITY'S COSTS ASSOCIATED WITH CAUSING THE PROPERTY TO BE SECURED AND/OR CLEANED. THE REMEDIES CONTEPLATED IN THIS PARAGRAPH ARE IN ADDITION TO ANY OTHER REMEDIES PROVIDED BY LAW.

A CERTIFICATE OF SUBSTANDARD HAS BEEN FILED AT THE COUNTY CLERKS OFFICE. A LIEN WILL BE PLACED AGAINST THE PROPERTY ASSOCIATED WITH THESE ACTIONS.

Pursuant to Section 14-3-5-3 a 2 d ROA 1994, you or any person having any title or legal interest in the building or structure may appeal this Notice and Order or any action of the Code Enforcement Section to the Housing Advisory and Appeals Committee. In the case of demolition, the appeal procedure shall be as set forth in Section 3-18-5 NMSA 1978. The appeal must be in writing and filed with the Mayor's office prior to the effective date of this order. The effective date of this order is: Oct 16, 2017.

A form for filing an appeal is available in the Code Enforcement Section office at 600 2<sup>nd</sup> St. NW, Suite 500. The form is not necessary as long as the required information is included in the appeal. Pursuant to Section 14-3-5-4 ROA 1994, the required information includes: the names of all appellants participating in the appeal; a brief statement setting forth the legal interest of each of the appellants in the building or the land involved in the appeal; a brief statement of the specific or action protested, together with any material facts supporting the appellant's contentions; a brief statement of the relief sought, and the reasons why it is claimed the protested order or action should be reversed, modified or otherwise set aside; the signatures of all parties named as appellants and their official mailing addresses; and a verification, by declaration under penalty of perjury, of at least one appellant as to the truth of the matters stated in the appeal.

An appeal of the Notice and Order will stay enforcement of that Notice and Order. Failure to file an appeal, however, shall constitute a waiver of the right to an administrative hearing and adjudication of Housing Advisory and Appeals Committee will be scheduled within ten (10) to sixty (60) days after receipt of the appeal. You will receive written notice of the time and place not less than ten (10) days prior to the date of the hearing. Only those matters or issues specifically raised by the appellant shall be considered in the hearing.

If you have any questions concerning this Notice and Order, or the cited violations, please call me at: (505) 924-3363. Please reference Notice and Order number CF-2017-026233.

Christopher Romero Code Enforcement Specialist (505) 924-3363

File Number: CF-2017-026233

Initial Print Date: Oct 2, 2017

Job Number: 049887118-001

### AFFIDAVIT OF SERVICE FOR POSTING AND MAILING OF NOTICE AND ORDER

STATE OF NEW MEXICO COUNTY OF BERNALILLO SS

I, Christopher Romero, being duly sworn upon Oath, state that on 10/2/2017, posted a copy of the Notice and

Order at 247 ESPANOLA ST NE, Albuquerque, NM, and mailed a copy of the Notice and Order by certified

mail to the owner on 10/2/2017.

Addressed to: SHAIN LAWRENCE V ETUX **1749 ALLEGHENY DR NE RIO RANCHO, NM 87144** 

Christopher Romero **Code Enforcement Specialist** Code Enforcement Division Planning Department City of Albuquerque (505) 924-3363

SUBSCRIBED AND SWORN TO me on this  $2 \sqrt{2}$ day of ( \_, 20<u>17\_\_</u>,

by Christopher Romero.

My commission expires 03-17-20.





In accordance with City Housing Code, which is City Ordinance enactment No. 34-1986 and codified at 14-3-1-1 ET. Seq. ROA 1994, the City of Albuquerque certifies that the property described below is a substandard building and that the owner(s) has/have been so notified.

Address of substandard building/legal description:

Property Address: 247 ESPANOLA ST NE, Albuquerque, NM 87108

Legal Description: LOT 26, BLOCK 4, SUBDIVISION LA MESA

Parcel Number (UPC): 10-190-5712319631032

Owner & Owner's	SHAIN LAWRENCE V ETUX
Address:	<b>1749 ALLEGHENY DR NE</b>
	RIO RANCHO, NM 87144

Processing Fee:\$50.00Filing Fee:\$25.00


٩

The property described above is in violation of the City Housing Code: **Notice and Order** dated **Sep 30, 2017** 

#### **Attached Are Copies of Findings**

Notice of the condition of the property was given to the owner in the following manner: Posted onto the front exterior of the building and mailed certified mail.

Andrew Garcia, Code Condpliance Manager Planning, Code Enforcement Division City of Albuquerque



STATE OF NEW MEXICO } SS COUNTY OF BERNALILLO

The foregoing instrument was acknowledged before me by Andrew Garcia this day of 40.00 20.17.

My Commission Expires 103-17-20

Doc# 2017099180 10/17/2017 11:14 AM Page: 1 of 6 NOT R \$25:00 Linda Stover, Bernalilo County