CITY of ALBUQUERQUE TWENTY FOURTH COUNCIL

COUNCIL BILL NO. <u>R-21-152</u> ENACTMENT NO.

SPONSORED BY: Brook Bassan, by request

1 RESOLUTION 2 A NUISANCE, SUBSTANDARD DWELLING OR STRUCTURE IN NEED OF 3 ABATEMENT AT 6816 INA DR NE 87109 WITHIN THE CITY LIMITS OF 4 ALBUQUERQUE, NEW MEXICO IS RUINED, DAMAGED AND DILAPIDATED AS 5 TO BE A MENACE TO THE PUBLIC COMFORT, HEALTH, PEACE OR SAFETY 6 AND THAT IT IS TO BE REQUIRED TO BE REMOVED.

7 WHEREAS, the building, structure or premises is located at 6816 Ina Dr. NE
8 Albuquerque, NM 87109, which is located and is more particularly described
9 as: 005 007JADE PARK MOBILE HOME SUB UNIT 9; and

10 WHEREAS, the Planning Department, Code Enforcement Division of the 11 City of Albuquerque has investigated the condition of said Building, structure 12 of premises and has found same to be so ruined, damaged and dilapidated 13 that it constitutes a menace to the public comfort, health, peace or safety and 14 warrants abatement and removal.

15 BE IT RESOLVED BY THE COUNCIL, THE GOVERNING BODY OF THE CITY OF16 ALBUQUERQUE:

Section 1. That the findings of said Code Enforcement, in regard to said building, structure or premises, be and are hereby approved and adopted and that said building, structure or premises is found to be ruined, damaged and dilapidated, as to be a menace to the public comfort, health, peace or safety pursuant to Section 3-18-5, N.M.S.A., 1978.

22 Section 2. That HOUSE THOMAS RICHARD, record owner of said 23 building, structure or premises shall commence removal of same within ten 24 (10) days after service of a copy of this Resolution or within said ten (10) day 25 period, file written objection to findings herein with the City Clerk/Recorder of 26 the City of Albuquerque, asking for a hearing before the City Council. Section 3. If there is a failure of compliance with the provision of Section 2 herein, the City of Albuquerque shall proceed to remove said building, structure or premises and abate said unsafe condition and the cost thereof shall constitute a lien against such property so removed and against said lot or parcel of land from which such removal be made, all as required and allowed by law.

Section 4. SEVERABILITY CLAUSE. If any section, paragraph, sentence, clause, word or phrase of this resolution is for any reason held to be invalid or unenforceable by any court of competent jurisdiction, such decision shall not affect the validity of the remaining provisions of this resolution. The Council hereby declares that it would have passed this resolution and each section, paragraph, sentence, clause, word or phrase thereof irrespective of any provisions being declared unconstitutional or otherwise invalid.

Bracketed/Strikethrough Material] - Deletion Bracketed/Underscored Material] - New



CITY OF ALBUQUERQUE Albuquerque, New Mexico Office of the Mayor

Mayor Timothy M. Keller

INTER-OFFICE MEMORANDUM

(DATE) December 11, 2020

TO: Cynthia Borrego, President, City Council

FROM: Timothy M. Keller, Mayor

SUBJECT: Resolution of Nuisance Abatement of a Substandard Building at: 6816 Ina Dr. NE Albuquerque NM 87109

The attached resolution requests that the building located at 6816 Ina DR NE Albuquerque, New Mexico 87109, be abated and removed. Council approval is required according to N.M.S.A. Section 3-18-5, 1978.

In the event that the owners fail to demolish the condemned structure, the Planning Department will contract for the demolition and place a lien on the property. The estimated cost for demolition is \$14,500.

I am submitting this resolution to the City Council for their consideration and action.

Resolution of Nuisance Abatement of a Substandard Building at: 6816 INA DR NE Albuquerque, New Mexico 87109

Approved as to Legal Form	1:
DateA. Aguilar, Jr.	3/15/2021 11:57 AM MDT Date
3/15/2021 11:39 AM MDT	
Date	
	15/2021 E:29 PM MDT Aquilar, Jr. Date 70 FistebauoA. Aguilar, Jr. City Attorney 3/15/2021 11:39 AM MDT

FISCAL IMPACT ANALYSIS

TITLE:	Address 6816	S Ina Dr Ne Albuque	rque NM 87109			R: X	<u>O:</u>
	Legal descrip	tion 005 007JADE P	ARK MOBILE HO	ME SUB UNIT 9		FUND:	110
					DEPT: Planning	_	
[×]	No measurab appropriations	le fiscal impact is an s.	ticipated, i.e., no ir	npact on fund bala	nce over and above	existing	
[]	(If Applicable) legislation is a	The estimated fisca as follows:	Il impact (defined a	as impact over and	above existing appro	opriations)	of this
				Fiscal Years			
			2021	2022	2023	Тс	otal
Base Salary/V Fringe Benefit		30.440%					
Subtotal Pers	onnei		-	-	-		-

Operating Expenses Property					-			-
Indirect Costs	%				-		-	-
Total Expenses		\$	•	\$		\$	- \$	-
[] Estimated revenues not affecte [X] Estimated revenue impact						1		
					-		-	-
								-
								-
			-		-		-	-
Total Revenue		\$		\$	-	\$	- \$	-
These estimates do <u>not</u>	include any	adjustment	for inflation	l.				

* Range if not easily quantifiable.

Number of Positions created

COMMENTS :

Structure poses an extreme hazard and is substandard and a nuisance to the neighborhood surrounding community and to inquisitive minors. The structure will continue to dilapidate causing life safety issues. This is a substandard and a nuisance property.

COMMENTS ON NON-MONETARY IMPACTS TO COMMUNITY/CITY GOVERNMENT:

PREPARED BY:

APPROVED:

Debbie Dombroski

Brennon Williams 02/OCT/2020 DIRECTOR (date)

FISCAL ANALYST

REVIEWED BY:

DocuSigned by:	DocuSigned by:	DocuSigned by:
UNDA CUTLER PADILLA	1 1 AUN 10 (1 1) Davie 3/18/2	2021 1.2 35 PHISMET BALMAN
FCDEFXEGUTIVE BUDGET ANALYST	BUDGET OFFICER (dat	e) <u>E02C282349CC47D</u>

Cover Analysis

1. What is it?

A substandard, nuisance structure located at 6816 Ina Dr. Ne and legally described as, 005 007JADE PARK MOBILE HOME SUB UNIT 9, in the City of Albuquerque.

2. What will this piece of legislation do?

Enable the removal of an unsafe, substandard, nuisance structure by a City Agency.

3. Why is this project needed?

Council approval is required for demolition of a Nuisance structure according to N.M.S.A. Section 3-18-5, 1998 and City Ordinance


4. How much will it cost and what is the funding source?

The estimated cost is \$14,500 from the General Fund. Upon completion of demolition, a lien will be filed which includes a demand for payment addressed to said owner(s).

5. Is there a revenue source associated with this Plan? If so, what level of income is projected?

None

DocuSign Envelope ID: 6676E65A-353D-4086-B9DB-27B362204454






CLAIM OF LIEN FOR BOARDING, CLEANUP OR REPAIR

The City of Albuquerque claims and establishes a lien on the property described below for the costs of boarding, cleaning a parcel of property or securing of a structure. The lien is provided by Ordinances numbered § 14-3-5-3(A)(2)(c)(4), 14-3-5-6(A)(3)(c) and 14-3-5-7 ROA. The filing, enforcement and priority of this lien are governed by New Mexico statutes § 3-36-1 ET. Seq. Pursuant to NMSA §§ 3-36-2, 3-36-6(M) and 3-36-7, once filed this lien attains a super-priority status with respect to all other interests in the property other than ad valorem property taxes or other special assessment liens.

Legal description: Address of Lien:	*005 007JADE PARK MOBILE HO 6816 INA DR NE	DME SUB UNIT 9
Owner & Owner's Address:	HOUSE THOMAS RICHARD 10240 BELNAP PL NE Albuquerque, NM 87114	
Certificate of Substandard Cost	ts: \$250.00	
Private Contractor Costs:		
Title Search:	\sim	
Posting & Publishing Fees:	Doc# 20130	70711 34 PM Page: 1 of 1 M. Toulouse Oliver, Bernalillo County
Filing Fees:	LIEN A S25.00	M Toulouse Oliver, Bernannin outre Ha Hus D
PRINCIPAL AMOUNT OF LIEN:	\$250.00) /~
CDBG Fund 205:		
The principal amount of this lier § 3-36-2(C) WITNESS my hand and seal th	is U day of the	ent (12%) per annum from date of filing. NMSA
4		Albuquerque (
to me personally known, who b Albuquerque, County of Bernali behalf, of sai	ay of the duly sworn or affirme illo, State of New Mexico, and the	OFFICIAL SEAL
Notary Public My commission expires		Stephania Apodaca (NOTARY PUBLIC STATE OF NEW MEXICO Hor Expires:

water.



Section: 14-3-2-3 (E): All accessories such as grab bars, towel bars, paper dispensers and soap dishes

and the like, provided on or within walls, shall be installed and sealed to protect structural elements from moisture.

<u>Section: 14-3-3-1 (A)</u>: Structural components of buildings shall be capable of resisting any and all forces and loads to which they may be subjected. All structural elements shall be proportioned and joined in accordance with the stress limitations and design criteria as specified in the Building Code.

Section: 14-3-3-1 (B): Every building shall be weather protected so as to provide-shelter for the occupants against the elements and to exclude dampness.

<u>Section: 14-3-3-1 (C):</u> All wood shall be protected against termite damage and decay as provided in the Building Code.

<u>Section: 14-3-3-2 (A)(1)(a)</u>: Every dwelling unit and guest room shall be provided with heating facilities capable of maintaining a room temperature of 70 degrees F at-a-point 3 feet-above the floor in all habitable rooms. A permanent, approved source of heat shall be installed to all bedrooms and habitable spaces in dwelling unit.

<u>Section 14-3-3-2 (A)(1)(b)</u> Unvented fuel-burning heaters shall not be permitted. All heating devices or appliances shall be of an approved type. A licensed contractor shall inspect, repair and or replace all heat sources to include water heater with all required permits being attained and all required inspections conducted.

<u>Section: 14-3-3-2 (A) (2) (a)</u>: All electrical equipment, wiring and appliances shall be installed and maintained in a safe manner in accordance with all applicable laws. All electrical equipment shall be of an approved type.

- All electrical wiring and wiring components shall be inspected by a licensed contractor and all necessary repairs shall be made or replace.
- Must provide a break box panel cover per manufacturing specifications.

<u>Section: 14-3-3-2(A)(2)(b)</u>: Every babitable room shall contain at least two supplied electric convenience outlets or one such convenience outlet and one supplied electric light fixture. Every water closet compartment, bathroom, laundry room, furnace room and public hallway shall contain at least one supplied electric light fixture.

- All electrical wiring and wiring components shall be inspected by a licensed contractor and all necessary repairs shall be made or replace.
- Replace all damaged and non-working electrical outlets.

<u>Section: 14-3-3-3 (A)(1)</u>: Every dwelling unit or guest room shall have access directly to the outside or to a public corridor. Provide a clear and accessible path to all exits.

<u>Section: 14-3-3-3 (A)(2)</u>: All buildings or portions thereof shall be provided with exits, exit ways and appurtenances as required by Chapter 33 of the Building Code.

<u>Section: 14-3-3-3(A)(3)</u>: Every sleeping room, below the fourth story, shall have at least one operable window or exterior door approved for emergency escape or rescue. The units shall be operable from the inside to provide a full clear opening without the use of separate tools.

• Entry door and sliding glass door locks and guide shall be repaired or

replaced so that doors operate smoothly without the use of extreme force or separate tools.

• Provide a clear and accessible path to all exits.

<u>Section: 14-3-3-3 (A)(4):</u> All escape or rescue windows from sleeping rooms shall have a minimum net clear opening of 5.7 square feet. The minimum net clear opening height dimension shall be 24 inches. The minimum net clear opening width dimension shall be 20 inches. These windows shall have a finished sill height not more than 44 inches above the floor.

<u>Section: 14-3-4-1</u>: Any building or portion thereof, including any dwelling unit, guest room, or white of rooms, or the premises on which the same is located, in which there exists any-of the following listed conditions to an extent that endangers the life, limb, health, property, safety or welfare of the public, or the occupants thereof shall be deemed and declared a SUBSTANDARD BUILDING.

<u>Section: 14-3-4-10:</u> Faulty materials of construction includes all materials or construction except those which are specifically allowed or approved by this Code and the Building Code, and which have been adequately maintained in good and safe condition.

<u>Section: 14-3-4-11:</u> Inadequate maintenance includes any building or portion thereof which is determined to be an unsafe building in accordance with Section 203 of the Uniform Administrative Code.

<u>Section: 14-3-4-13:</u> Inadequate fire-protection includes all buildings or portions thereof which are not provided with the fire-resistive construction or fire-extinguishing systems or equipment required by this code and the Chief of the Fire Department.

<u>Section: 14-3-4-2 (C)</u>: Inadequate sanitation includes tack of, or not properly operative kitchen sink. Make necessary repairs as required.

<u>Section: 14-3-4-2(E)</u>: Inadequate sanitation includes lack of hot and cold running water to plumbing fixtures in a dwelling unit. A licensed contractor shall inspect, repair and or replace water heater with all required permits being attained and all required inspections conducted.

<u>Section: 14-3-4-2 (F):</u> Inadequate sanitation includes lack of adequate heating facilities. Dwelling shall be provided with an approved, adequate and permanent source of heat.

<u>Section: 14-3-4-2 (G):</u> Inadequate sanitation includes lack of, or improper operation of required ventilating equipment.

<u>Section: 14-3-4-2 (I-I):</u> Inadequate sanitation includes lack of minimum amounts of natural light and ventilation ventilation by this Code.

Section: 14-3-4-2(J): Inadequate sanitation includes lack of required electrical lighting.

Scction: 14-3-4-2(L): Inadequate sanitation includes general dilapidation or inadequate maintenance.

- All weeds, trash, debris, litter, and excessive storage shall be removed from property and dwelling.
- This includes any inoperable vehicles on property.

<u>Section: 14-3-4-3 (I)</u>: Every inside and outside stair, every porch, and every appurtenance thereto shall be safe to use and capable of supporting the load that normal use may cause to be placed thereon.

<u>Section 14-3-4-3 (K)</u> Every interior wall and ceiling is free of holes and large cracks. Every interior wall and ceiling is free of loose plaster and other structural material, the collapse of which might constitute an accident hazard.

All missing, fallen, and rotted drywall shall be repaired or replaced to include tape, texture and paint. As required.

Section: 14-3-4-4: Any nuisance as defined in this code.

Due to the violations listed in this Notice and Order, it has been determined that the dwelling is Substandard. Dwelling has been in a dilapidated state for an extended period of time with in adequate maintenance and is creating a nuisance to the neighborhood and surrounding community.

<u>Section: 14-3-4-5</u>: Hazardous wiring includes all wiring except that which conformed with all applicable laws in effect at the time of installation and which has been maintained in good condition and is being used in a safe manner.

Prior to unit being occupied power must be restored by PNM electrical services.

<u>Section: 14-3-4-6</u>: Hazardous plumbing includes all plumbing except that which conformed with all applicable laws in effect at the time of installation and which has been maintained in good condition and which is free of cross-connections and siphonage between fixtures.

Prior to unit being occupied water services shall be reactivated by the Albuquerque Bernalillo County Water Utility Authority and provide both hot and cold water to faucets.

<u>Section: 14-3-4-7</u>: Hazardous mechanical equipment includes all mechanical equipment, including vents, except that which conformed with all appliedble laws in effect at the time of installation and which has been maintained in a good and safe condition. **Prior to unit being occupied gas fuel must be restored by NM Gas Company**.

<u>Section: 14-3-4-8(A)</u>: Faulty weather protection includes deteriorated or ineffective waterproofing of exterior walls, roof, foundations or floors, including broken windows, doors and basement hatchways. All broken and missing windows and doors shall be repaired or replaced.

<u>Section: 14-3-4-8(B)</u>: Faulty weather protection includes defective or lack of weather protection for exterior wall coverings, including lack of paint, or weathering due to lack of paint or other approved protective covering.

<u>Section: 14-3-4-8(C)</u>: Faulty weather protection includes broken, rotted, split or buckled exterior wall coverings or roof coverings.

Section: 14-3-5-12: All buildings or portions thereof which are determined to be substandard as defined in this code, are hereby declared to be nuisances and shall be abated by repair, rehabilitation, demolition, removal, or securing all accessible openings and entrances to building in accordance with the procedure as provided herein. Any building that has been determined to be substandard and which has been abated by securing all accessible openings and entrances shall be repaired, rehabilitated, demolished, or removed within 12 months of being secured. The failure to repair, rehabilitate, demolish or remove such

building within 12 months shall be prima facie evidence that the building is a menace to the public comfort, health, peace, or safety and should be condemned. At the first City Council meeting following the 12 month period the administration shall present City Council with a Resolution of Condemnation as provided for in Section 3-18-5 NMSA 1978 and proceed with condemnation as provided for under that statute.

*** Due to the violations listed in this Notice and Order, it has been determined that the dwelling is Substandard and shall not be occupied, only work shall be preformed during the hours of 8am thru 6pm daily.

CERTIFIED MAIL (Signature) Brennon Williams. Code Compliance Manager Code Enforcement Division Planning Department 4. S. A. S. A File foregoing instrument was acknowledged before me this 12 day of g 2013 by (Printed Name) Notary Publie STATE OF NEW MEXICO COUNTY OF BERNALILLO My commission expires ____/14/1.



















